



QT-4085 T-980



Philips Domestic Appliances and Personal Care

ServiceManual

PRODUCT INFORMATION

- Rechargeable Beardtrimmer

Safety

- This product meets the requirements regarding interference suppression on radio and TV.
- After the product has been repaired, it should function properly and has to meet the safety requirements as officially laid down at this moment.

TECHNICAL INFORMATION

- No specific issues.

DISASSEMBLY- AND RE-ASSEMBLY ADVISE

- No specific issues.

REPAIR INSTRUCTION

- For this Hairclipper only the parts shown in the exploded view will be supplied.


OPTIONAL (accessories)


- No specific issues.



QT-4085 T-980













Pos	Service code	Description
1	9965 000 42794	Comb assy
2	9965 000 42792	Cutter assy
3	9965 000 42793	Collection chamber assy - EU
	9965 000 42815	Collection chamber assy - USA
4	9965 000 42795	Profiler assy
5	4203 035 79560	Adapter for QT4085 - EU
	4203 035 79870	Adapter for QT4085 - UK
	4203 035 79590	Adapter for QT4085 - CDN
	4203 035 79570	Adapter for T980 - US
6	4822 479 30183	Cleaning brush